

Regulatory Reform (Fire Safety) Order 2005

Pheasey Park Farm Primary School, Wimperis Way, Walsall, B43 7DH.

Appendix B

Provision of information to employers and the self employed from outside undertakings

In accordance with Article 20 of the above order, we have a duty to inform you of any risks to you or your employees, identified in the fire risk assessment for our workplace and the preventative and protective measures employed within the building in respect of fire safety.

Please find presented below the preventative and protective measures employed at the school to protect all relevant persons in the event of fire in the building.

Means of escape in case of fire

Due to nature of the premises, the travel distances involved and the number of children and staff the means of escape from the building is considered acceptable. There are three assembly points for the school. A palisade fence secures the perimeter of the premises. All staff are aware of the evacuation procedure and fire drills are carried out once per term and the results recorded in a log book.

Fire alarm and detection

The School has an electrical fire alarm system fitted conforming to BS 5839 with smoke detection. The Indicator Panel is located in the entrance lobby. The fire alarm is tested on a weekly basis using a different call point each week.

Emergency Lighting

Emergency lighting is provided throughout the school.